### Unofficial Translation

### (Garuda Sign)

# Department of Internal Trade Notification Re: to examine and certify Measurement Gauge to examine outside B.E.2545

\_\_\_\_\_

The applicant may request the Competent Official to examine outside the Central Bureau or Branch Bureau, Measurement Gauge must be of the type and number specified below.

### Weighing machine

1. Automatic weighing machine Semi-automatic, Except for springs weighing machine.

| (1) displaying weight not more than 100 kilogrammer          | not less than | 50 machines  |
|--|---------------|--------------|
| (1) displaying weight not more than 100 kilogrammes          | not less than | 30 machines  |
| (2) displaying weight more than 100 kilogrammes              |               |              |
| but not more than 2,000 kilogrammes                          | not less than | 10 machines  |
| (3) displaying weight more than 2,00 kilogrammes             | not less than | 5 machines   |
| 2. Springs weighing machine.                                 |               |              |
| (1) displaying weight not more than 20 kilogrammes           | not less than | 300 machines |
| (2) displaying weight more than 20 kilogrammes               | not less than | 200 machines |
| 3. Non-automatic weighing machine except weighing machine    |               |              |
| Measuring the percentage of starch in the head               |               |              |
| (1) displaying weight not more than 100 kilogrammes          | not less than | 100 machines |
| (2) displaying weight more than 100 kilogrammes              |               |              |
| but not more than 2,000 kilogrammes                          | not less than | 10 machines  |
| (3) displaying weight more than 2,00 kilogrammes             | not less than | 5 machines   |
| 4. Weighing machine measures the percentage of starch in the | not less than | 20 machines  |
| tubers   |               |              |
| 5. Pendulum  |               |              |
| (1) displaying weight not more than 10 kilogrammes           | not less than | 50 pendulum  |
| (2) displaying weight more than 10 kilogrammes               | not less than | 20 pendulum  |

## Volume Measuring Tool

| 1. Liquid measuring machine Non-classified type             |               |              |
|---|---------------|--------------|
| (1) displaying volume not more than 1 litres                | not less than | 100 machines |
| (2) displaying volume more than 1 litres                    | not less than | 50 machines  |
| 2. Measure the fuel and engine oil                          | not less than | 200 machines |
| 3. Measure of the fuel pump                                 | not less than | 100 machines |
| Measurer  |               |              |
| 1. Length measurer type metal belt roll back type automatic |               |              |
| fiberglass And foldable Display not more than 5 meters      | not less than | 300 machines |
| 2. Volume meter of lubricant                                | not less than | 100 machines |
| 3. Volume measurer  |               |              |
| (1) displaying Diameter not more than 25 millimeter         | not less than | 300 machines |
| (2) displaying Diameter more than 25 millimeter             |               |              |
| but not more than 80 millimeter                             | not less than | 50 machines  |
| (3) displaying Diameter more than 80 millimeter             | not less than | 10 machines  |